ALINX	Alinx - Product Change Notification (PCN)	No.: PCN_SP_2025-002 Date: 07.08.2025

Affected Products	
Product Series	Development Board (AXU9EGB, AXU15EGB)
Affected Product Model	AXU9EGB, AXU15EGB
Affected Parts	AXU9EGB V2.0, AXU15EGB V2.0
Replacement Parts	AXU9EGB V2.1, AXU15EGB V2.1

Type of PCN, Description and expected impact for customers	
Type of PCN	**A – Post on Alinx's Website** ☐ Removal of Product Model (if no customer is affected) ☐ Minor Revision without impact on customer ☐ Other, specify: **B – Inform current customers** ☐ Increase of minimum order quantity (MOQ) ☐ Status Changes to end-of-life (EOL) ☐ Removal of Product Model (if customer is affected) ☐ Major Revision roll-out ☐ Minor Revision with impact on customer ☐ Other, specify: **C – Inform all affected customers** ☐ Security related bug / Major non-conformance to specification ☐ Other, specify:
Description of change	Fan holes enlarged to solder four copper pillars on the carrier board.
Reason for change	To prevent SoM PCB deformation during fan screw installation.
Expected impact on customer	N/A
Forecasted key milestones	Last Time Buy (LTB): N/A due to unavailability of components. Last Time Ship (LTS) date: N/A, according to components availability.

Details of change	
Details	N/A ***Please refer to product user manual and schematics for more details.***

Contact
If you have any questions or require additional information, please contact technical@alinx.com. ***Web: https://www.en.alinx.com/***

Alinx Electronic Limited