








| No. | Description of Revision | Date | Name |
|-----|-------------------------|------|------|
| △ | | | |
| △ | | | |



Recommended Board Pattern




The Tolerance Limit of Terminal on SMD Plane



Plug Assembly(Reference Spec')

| No. | Material | Finish | Remark |
|-----|----------------------|------------------|--------|
| 1 | Thermoplastic(Black) | UL94V-0 | |
| 2 | Copper Alloy | Selective Gold | |
| 3 | Stainless Steel | SnPb over Nickel | |



| SnPb Plated | | | | | | | | | | | | | | | | | | | |
|-------------|----------------|----------------------------|--|-------------------|--|-------------|--|-------------------------------|--|------------|--|---------|--|----------------|--|-----------|--|-----------------|--|
| Check List | | | | No. | | Description | | Q'ty | | Material | | Size | | Heat Treatment | | Remark | | | |
| No | Spec' | Remarks | | General Tolerance | | Dimension | | Scale | | 4/1 | | Unit | | mm | | Item Name | | 3050Series | |
| A | +0.00, ~ -0.05 | Metal Cover Bending Limit | | 0. | | ±0.2 | | Date | | 2000.08.17 | | | | | | | | 3050-24R-0.5MSF | |
| B | 0.00 ~ 0.03 | Contact Terminal Gap Limit | | 0.00 | | ±0.05 | | Drawn | | Designed | | Checked | | Reviewed | | Approved | | A0511400.DWG | |
| C | 15.60 ~ 15.90 | Metal Cover Inside Width | | 0.000 | | ±0.04 | | h.s. Choi | | | | | | | | S / N | | A0511400.DWG | |
| | | | | 0.0000 | | ±0.005 | | HYUNDAI ELECTRONICS CO., LTD. | | | | | | | | D / N | | HCA05 - 11400 | |